



Although the geotechnical reports states that seeps were never observed, I photographed this seep (red arrow) at the toe of the landslide hazard area in the Regatta Estates Tract 992 utility corridor. Homes along 133rd Place W are seen to the east.

Photo March 8, 2016 by William Lider

